

## PRIDE OF PLACE 2017

Facility # 126Name: Agnes Hodge

Priority	Component Description	Component Deficiency	Estimate
1	Flooring, ebase # 139, 140 & 142	old carpet, worn out	\$ 6,100.00
2	Repair / replace 50 lockers, 2nd floor	lockers damaged, broken	\$ 7,063.00
3	Roller blinds, ebase # 161, 204 & 205	curtains damaged, beyond repair	\$ 4,600.00

Facility # 157Name: Banbury Heights

Priority	Component Description	Component Deficiency	Estimate
1	Blinds for the following rooms: Portapac room 106 EBase 139, 206, 209, 210, 211, 213, 230, 235, 237	Old and worn out	\$ 3,000.00
2	carpet in 206 (upstairs LRT office) replaced with vinyl laminate	Old and worn out	\$ 3,000.00
3	Scrap stucco and paint ,replacement in main foyer paint on door trim, hall paint	Stucco is dirty and stained doors and trim is worn and dirty	Maintenance

Facility # 101Name: Bellview

Priority	Component Description	Component Deficiency	Estimate
1	Locks, re-key interior doors	different locks throughout the school, make same	\$ 2,200.00
2	Two more doors for pod	complete prior project, improve lockdown plan	\$ 7,600.00
3	Roller blinds, pod area and doors	improve lockdown	\$ 2,875.00
4	Cameras, DVR, high priority areas	security (approx. 6 cameras )	\$ 15,300.00

PRIDE OF PLACE 2017

Facility # 512

Name: Bloomsburg

Priority	Component Description	Component Deficiency	Estimate
2	Paint classroom, #8	needs painting	\$ 2,300.00
3	Acrylic school lettering	existing ones bad shape, wooden , rotting	\$ 650.00

Facility # 513

Name: Boston

Priority	Component Description	Component Deficiency	Estimate
1	Ceiling fans, ebase # 32 & 33	last 2 classrooms in school without fans	\$ 1,130.00
2	Painting offices, ebase # 42 & 43	walls require patching and painting	\$ 2,000.00

Facility # 156

Name: Branlyn

Priority	Component Description	Component Deficiency	Estimate
2	Replace the flooring in the library. Ebase number 2024	Old and worn out	\$ 10,000.00

Facility # 106

Name: Brier Park

Priority	Component Description	Component Deficiency	Estimate
1	NO SUBMISSION		
2	Painting		\$ 2,000.00

## PRIDE OF PLACE 2017

Facility # 104Name: Burford

Priority	Component Description	Component Deficiency	Estimate
1	Repair plaster and paint hallways outside of classroom areas first and second floors	Plaster on walls is chipped and continues to erode	Maintenance
2	Paint in gym	Blackboards, bulletin boards and Velcro strips have been removed and relocated	\$ 5,000.00
3	Replace taps to metered style in upstairs Boys Washroom	Taps have been left on with plugged drains	Maintenance
4	Level floor and replace flooring in room # 108 Ebase 1059	The floor has a significant bump in it which is a trip hazard	\$ 7,000.00

Facility # 713Name: Caledonia Centennial PS

Priority	Component Description	Component Deficiency	Estimate
2	Main floor corridors	Old paint	\$ 4,200.00
3	Remove VAT and replace flooring room 5	Old VAT floor	\$ 5,400.00

Facility # 108Name: Cedarland

Priority	Component Description	Component Deficiency	Estimate
	NO SUBMISSION		
	Painting		\$ 2,000.00

Facility # 109Name: Centennial Grandwoodlands

Priority	Component Description	Component Deficiency	Estimate
1	Paint all washrooms/stalls (including staff	Looking dingy, not well cared for by students/staff	\$ 3,000.00
2	Paint/repair all door frames and doors.	Uniformity, cleanliness. Does not presently look good	\$ 3,000.00
3	Repair/replace asphalt in back of school.	Breaking/cracking/uneven pavement.	Capital

## PRIDE OF PLACE 2017

Facility # 110Name: Central Brantford

Priority	Component Description	Component Deficiency	Estimate
1	Walls, stair components - Stair 116	Worn, peeling paint, stairs in poor condition	\$ 1,000.00
2	Paint 1st and 2nd floor doors and frames	Worn, peeling paint	Maintenance

Facility # 161Name: Cobblestone

Priority	Component Description	Component Deficiency	Estimate
2	would like to add cupboards with doors above the cubbies in the kindergarten rooms	Additional storage space	\$ 1,000.00

Facility # 539Name: Courtland

Priority	Component Description	Component Deficiency	Estimate
1	Exterior doors in vestibule # 30	frame rotted, doors not functioning properly	Capital

Facility # 543Name: Delhi Public

Priority	Component Description	Component Deficiency	Estimate
1	Painting, hallways, trim	paint chipped, peeling, needs refreshing	\$ 10,000.00
2	Roller blinds, ebase #38, 59,65, P-8086	old verticals broke, not functioning	\$ 4,475.00

## PRIDE OF PLACE 2017

Facility # 114Name: Dufferin

Priority	Component Description	Component Deficiency	Estimate
	NO SUBMISSION		
	Painting		\$ 2,000.00

Facility # 115Name: Echo Place

Priority	Component Description	Component Deficiency	Estimate
1	New Sign read-o-graph	Old one falling apart - unrepairable	\$ 1,200.00

Facility # 164Name: Ecole Confederation

Priority	Component Description	Component Deficiency	Estimate
1	Gate and fence to enclose Kindergarten end of yard	The area alongside Ewing drive is currently open. This is the area where our Kindergarten students play at recess	\$ 6,000.00
2	Build shelving in gym storage room	There is currently no shelving in the gym storage room	\$ 2,000.00
3	Reface/repaint lockers in Jr./Intermediate hallway	Many locker door hinges have rusted off and the doors cannot be reinstalled	\$ 3,000.00
4	Renovate kitchen to accommodate space for fridges	Current space will not accommodate a full size appliance	Maintenance

Facility # 103Name: GELA Rawdon

Priority	Component Description	Component Deficiency	Estimate
1	2 security cameras	Need more	\$ 3,600.00
2	Office and classroom blinds	Old drapery	\$ 1,000.00

PRIDE OF PLACE 2017

Facility # 119

Name: Glen Morris

Priority	Component Description	Component Deficiency	Estimate
2	Corner play area needs to be removed	This area is farthest from the school, not allowing quick access to students during unsafe situations	Maintenance
3	Painting of doors and frames	Patches of chipped paint on all door frames	\$ 5,000.00

Facility # 120

Name: Graham Bell

Priority	Component Description	Component Deficiency	Estimate
1	Paint classrooms and cloakrooms first floor / second floor	Paint is old and peeling	\$ 5,000.00
2	Paint main office secretary / Principals	Colour needs to be more inviting	\$ 1,000.00
3	Repair window sills throughout the school	Sills are crumbling	Capital
5	Repair exterior eavestroughs and down spouts	Down spouts are old ,rusted paint is peeling	\$ 3,000.00

Facility # 121

Name: Grandview

Priority	Component Description	Component Deficiency	Estimate
2	Paint Gym (ebase 137) and ebase 125	Gym paint starting to flake off	\$ 8,000.00

Facility # 123

Name: Greenbrier

Priority	Component Description	Component Deficiency	Estimate
2	Paint all doors and door frames in main building	To clean up the school making it more inviting	\$ 5,000.00
3	Re-Paving outside from front to back	Current pavement is broken up	Capital

PRIDE OF PLACE 2017

Facility # 722

Name: HAGERSVILLE ES

Priority	Component Description	Component Deficiency	Estimate
1	Sidewalk to crossing at Parkview	Old half complete asphalt sidewalk	\$ 3,000.00
2	Front yard	Needs new topsoil, grass	Maintenance
3	Paint Rooms 11,15	Old paint	\$ 1,500.00
4	Ceilings Rooms 11,14	Need to be cleaned	\$ 1,000.00

Facility # 538

Name: Houghton

Priority	Component Description	Component Deficiency	Estimate
1	Asphalt driveway, parking lot	extremely bad condition	Capital
2	Two swipe access cards	support safe school, control supervision	\$ 5,600.00
3	Painting, frames, doors, ebase 26 & 42	complete last section of school	\$ 6,700.00

Facility # 125

Name: James Hillier

Priority	Component Description	Component Deficiency	Estimate
1	Install changeroom doors (Girls and Boys) and signage.	Currently there are no changeroom doors on either the Girls or Boys changerooms	\$ 4,000.00

Facility # 718

Name: Jarvis

Priority	Component Description	Component Deficiency	Estimate
1	Paint Classrooms	Old faded, dated paint	\$ 6,000.00
2	Boys and Girls WR's 37,45	Replace old stalls, counters, sinks, paint	\$ 3,000.00

## PRIDE OF PLACE 2017

Facility # 719Name: JL Mitchener

Priority	Component Description	Component Deficiency	Estimate
1	New blinds in various rooms	New blinds to replace old curtains	\$ 3,000.00
2	Area rugs - 1064,1065	Replace dirty ones	\$ 500.00
3	Repaint Staff Room 1052 and Boys WR 1048	Refresh paint	\$ 2,000.00

Facility # 129Name: King George

Priority	Component Description	Component Deficiency	Estimate
1	New blinds in rooms	Old drapery	\$ 1,500.00
2	Flooring	Replace carpeted classroom floor	\$ 4,600.00

Facility # 542Name: Lakewood

Priority	Component Description	Component Deficiency	Estimate
1	Flooring, ebase # 1104, 1105, 1108 & 1109	large gaps, floor separating	\$ 11,413.00
3	Ceiling fans, 2nd. Floor	there isn't any, help with air circulation	\$ 7,000.00

Facility # 534Name: Langton Public

Priority	Component Description	Component Deficiency	Estimate
1	Painting, ebase # 29 & 51	peeling paint, numerous areas to patch	\$ 4,600.00
2	Flooring, ebase #46	needs replacing, poor shape	\$ 1,350.00



## PRIDE OF PLACE 2017

Facility # 130Name: Lansdowne

Priority	Component Description	Component Deficiency	Estimate
1	Remove fencing and install a ramp to sidewalk	Safe access to footpath and sidewalk when exiting the playground next to the loop.	\$ 3,000.00
2	Install Roller Blinds in ebase 06 and 29	Existing blinds are broken No blind in place in some rooms	\$ 1,500.00
3	Replace Windows in Kindergarten ebase 48	Seals are gone and windows were to be replaced in original Kindergarten rebuild, but was not done	Capital
4	Replace Kindergarten Entry Door	Original old style door does not seal	Capital
5	Replace window seating in Kindergarten ebase 52	Seating is worn and can no longer be cleaned properly	Maintenance

Facility # 527Name: Lynndale Hts.

Priority	Component Description	Component Deficiency	Estimate
1	Fencing	contain runners	\$ 4,700.00
2	Washroom renovation, ebase #70	walls, floor in poor shape, countertop	\$ 6,875.00
3	Ceiling fans, ebase #4, 7, E18 & E26	continuation of fans throughout the school	\$ 2,260.00

Facility # 132Name: Major Ballachey

Priority	Component Description	Component Deficiency	Estimate
1	Blinds for library area rooms 113,114,115	Old, damaged aluminum blinds	\$ 4,000.00
2	Paint gym front facade	Old paint	\$ 1,000.00
3	Paint basement corridor doors, frames	Old paint	\$ 2,000.00
4	paint stairway components Stairwell 127	Old paint	\$ 2,000.00

## PRIDE OF PLACE 2017

Facility # 134Name: Mt. Pleasant

Priority	Component Description	Component Deficiency	Estimate
1	The eaves at the front of the school	They are old, dirty and dysfunctional and not draining properly	\$ 3,000.00
2	Paint the stage	The stage has several different colours and is dirty and dingy	\$ 6,000.00
3	Paint the staff room	Paint is worn and dirty looking	\$ 1,000.00

Facility # 136Name: North Ward

Priority	Component Description	Component Deficiency	Estimate
2	Replace ceiling tiles and recess the lights in foyer 18.	Tiles are cracked, lifted and stained	\$ 2,000.00
3	Paint corridor 75 and 76.	This would complete the painting of the whole school	\$ 5,000.00

Facility # 148Name: Oakland - Scotland

Priority	Component Description	Component Deficiency	Estimate
	NO SUBMISSION		
	Painting		\$ 2,000.00

Facility # 721Name: Oneida Central

Priority	Component Description	Component Deficiency	Estimate
1	West exit doors - Vestibule 08	Old doors need to be replaced	Capital
2	Swipes/ electronic latch, Vestibule 08, Corridor 15	Don't exist	\$ 4,500.00
5	Window coverings - primary classrooms	Old drapery	\$ 1,500.00

Facility # 139Name: Onondaga Brant

Priority	Component Description	Component Deficiency	Estimate
1	Painting of various areas of school	Old, faded paint	\$ 10,000.00

PRIDE OF PLACE 2017

Facility # 140

Name: Paris Central

Priority	Component Description	Component Deficiency	Estimate
1	Paint Library ebase 122	Has not been painted in over 20 years old and worn	\$ 6,000.00
2	Replace carpeting in main office ebase 104,105,106,108	First impression is not positive, carpet worn and stained	\$ 6,000.00

Facility # 537

Name: Port Rowan

Priority	Component Description	Component Deficiency	Estimate
1	Repair piping in staff washroom	Falling apart	Maintenance
2	Replace windows, rooms # 10, 11 & 12	seals gone	Capital
3	Replace counter tops, # 10, 11 & 12	old , needs replacing	\$ 4,800.00

Facility # 142

Name: Prince Charles

Priority	Component Description	Component Deficiency	Estimate
1	Security Cameras and communications	School is vandalized on a regular basis	\$ 10,000.00
2	2 tetherball nets for the students on the yard	We continue to give options to our students to be active	\$ 1,500.00

Facility # 143

Name: Princess Elizabeth

Priority	Component Description	Component Deficiency	Estimate
2	Roller blinds, ebase # 24, 50, 53, 56 & 60	none , need for lock down	\$ 2,600.00
3	Flooring, ebase #05, # 60	bamboo, bad shape	\$ 2,900.00
4	Paint staff room, replace sink & counter top	paint peeling, sink, top in bad shape	\$ 4,320.00

PRIDE OF PLACE 2017

Facility # 723

Name: Rainham

Priority	Component Description	Component Deficiency	Estimate
1	Replace windows, Rooms 27,27A,28	Old original windows	Capital
2	Gym wall logo or inspirational quotes	Doesn't exist	\$ 4,000.00

Facility # 733

Name: River Heights

Priority	Component Description	Component Deficiency	Estimate
1	Floors - Boys WR 024, Girls WR 017	Floor badly stained and smells	\$ 7,500.00
2	Staff/Visitors WR's	need upgrading	\$ 4,000.00
3	Front concrete paver sidewalk	need upgrading	Capital
5	New sidewalks and asphalt	Old, uneven	Capital
6	West end stairwell floors	Old landings, treads	\$ 5,000.00
8	Window coverings room 10	Old drapery	\$ 1,200.00

Facility # 146

Name: Russell Reid

Priority	Component Description	Component Deficiency	Estimate
1	Replace front entrance doors and the three side doors	Doors are 52 years old and not very efficient. Lock doesn't work	Capital
2	Painting classrooms and hallway, ebase 23, 24, 25 and 228	Walls are marked, scratched, not pleasing to the eye.	\$ 5,000.00

Facility # 160

Name: Ryerson Hts

Priority	Component Description	Component Deficiency	Estimate
	NO SUBMISSION		
	Painting		\$ 2,000.00

## PRIDE OF PLACE 2017

Facility # 724Name: Seneca Central

Priority	Component Description	Component Deficiency	Estimate
1	School sign (unlit)	Old sign worn and in disrepair	\$ 5,000.00
3	Ceiling fans in some classrooms	Don't exist	\$ 4,000.00

Facility # 150Name: St. George - German

Priority	Component Description	Component Deficiency	Estimate
1	Replace old tile/carpet floors in staff room 71.	Carpet is stained and old	\$ 4,500.00
2	Paint doors and frames in hallway/office areas	Painting is chipped and peeling	\$ 10,000.00

Facility # 519Name: Teeterville

Priority	Component Description	Component Deficiency	Estimate
1	cabinet, sink, new countertop	old, falling apart	\$ 2,400.00
2	Roller blinds	there isn't any	\$ 1,900.00
3	Painting, staff washrooms	paint peeling, chipped	\$ 960.00

PRIDE OF PLACE 2017

Facility # 715

Name: Thompson Creek

Priority	Component Description	Component Deficiency	Estimate
1	Fans for top floor classrooms	Too hot	\$ 2,500.00
2	Projection screen - gym	Old, torn	\$ 2,000.00
3	Remove and replace VAT Floor in room 205	Old VAT, lifting up	\$ 6,000.00
6	Classroom 11 receptacles	Not enough	Maintenance
7	Gym folding doors	Vinyl peeling, needs repairs	Capital
8	Classroom cabinetry	veneer peeling - eye sore	Maintenance

Facility # 726

Name: Walpole North

Priority	Component Description	Component Deficiency	Estimate
1	Corridor ceiling system	Old, rusty	\$ 5,000.00
2	Breezeway doors - vestibules 11 and 17	Old, wood doors	Capital
3	Paint Classroom 14	Old paint	\$ 1,500.00
4	Paint Classroom 19	Old paint	\$ 1,500.00

Facility # 529

Name: Walsh

Priority	Component Description	Component Deficiency	Estimate
1	Painting, classrooms	painting flaking, needs refreshing	\$5,000.00
2	Ceiling tiles, lighting	needs brightening up	\$8,000.00

## PRIDE OF PLACE 2017

Facility # 162Name: Walter Gretzky

Priority	Component Description	Component Deficiency	Estimate
1	Fencing	non there	\$9,040.00

Facility # 516Name: Waterford Public

Priority	Component Description	Component Deficiency	Estimate
1	Outdoor lighting	provide better lighting for playground	\$ 1,000.00
2	Gym panels, exterior	panels in rough condition, asbestos bearing	Capital

Facility # 154Name: Woodman

Priority	Component Description	Component Deficiency	Estimate
1	More fence along east boundary	Doesn't exist	\$ 6,500.00
2	Blind on FDK doors	Lockdown	\$ 150.00
3	Painted asphalt playground games	Old and faded	\$ 1,500.00
4	Security camera	Improved security	\$ 1,800.00

Facility # 271Name: BCI

Priority	Component Description	Component Deficiency	Estimate
1	Lockers Tech Hall	The lockers are the original lockers from 1963. Many are broken or nailed shut.	\$10,000.00

## PRIDE OF PLACE 2017

Facility # 729Name: CSS

Priority	Component Description	Component Deficiency	Estimate
2	Stage floor	Needs refinishing	\$ 8,500.00
3	Concrete patio	Concrete cracked, breaking up	\$ 10,000.00

Facility # 505Name: DelhiDSS

Priority	Component Description	Component Deficiency	Estimate
1	Painting, classrooms, hallway	paint peeling, very outdated	\$ 13,927.00
2	New shower heads, lighting	dingy, dark,	\$ 3,200.00
3	Paving, circular drive	needs widening, add more parking	Capital

Facility # 730Name: DunvilleSS

Priority	Component Description	Component Deficiency	Estimate
1	Existing library shelving	Relocate within library	\$ 2,500.00
2	HCP door opener on accessible WR	Doesn't exist	Capital
3	Classroom curtains	Old curtains	\$ 1,100.00
4	Gym Walls	Old paint	\$ 6,000.00

Facility # 731Name: HSS

Priority	Component Description	Component Deficiency	Estimate
1	Front yard old pea stone - replace with concrete	Area is an eyesore	\$ 5,000.00
2	Upper wood paneling main gym walls	Wood is dark and finish deteriorating	\$ 4,000.00
3	Lockers - Corridor 1041	Reface - refinish	\$ 10,000.00



PRIDE OF PLACE 2017

Facility # 732

Name: MPSS

Priority	Component Description	Component Deficiency	Estimate
1	Blinds for library	Old curtains	\$ 2,500.00
2	Blinds for portable 13	Old curtains	\$ 500.00
3	Paint doors 1057,1058,1065	Paint old	\$ 300.00
4	Paint daycare foyer 1173	Paint old	\$ 1,500.00
5	Blinds in back hall (3) 1175	No curtains - security camera glare	\$ 2,000.00
6	Paint doors on second floor	Paint old	\$ 1,500.00
7	Paint Rooms 2051,2054,2055	Paint old	\$ 4,000.00

Facility # 274

Name: NPCVS

Priority	Component Description	Component Deficiency	Estimate
1	Replace tile flooring upstairs and downstairs at NPC with poured epoxy flooring, also (Ebase 1150)	Work deferred due to projects scheduled during summer break	

Facility # 275

Name: PDHS

Priority	Component Description	Component Deficiency	Estimate
2	Bring the small gym mezzanine railing up to code by adding a bar to the railing.	The railing isn't currently to code and we are unable to use the mezzanine	\$ 6,000.00
3	Reflective window film on the 3rd floor science classrooms with southern exposure facing the courtyard	The temperature gets very hot in these rooms from the southern exposure	\$ 1,000.00
4	Replace the ceiling tiles and repair and paint the ceiling in the 100's hall from Phys Ed to COOP	The ceiling is very old, dirty and decrepit. This is one of the major public entrances into the school	\$ 5,000.00
5	Replace the carpeting in the main offices and the guidance offices	The carpet is very old, dirty and worn.	\$ 5,000.00
6	Top Dress the Football Field and do maintenance to the sprinkler system	Field is uneven and has pits and holes. The sprinkler didn't work properly this summer	\$ 5,000.00

## PRIDE OF PLACE 2017

Facility # 276Name: PJCVS

Priority	Component Description	Component Deficiency	Estimate
2	Stage Floor	Needs refinishing	\$ 9,000.00
3	Stage drapery	Old, stained	\$ 7,000.00

Facility # 501Name: SCS

Priority	Component Description	Component Deficiency	Estimate
1	Flooring, various classrooms	old ,worn out, some are asbestos bearing	\$ 11,340.00
2	Painting, various classrooms, mural	paint peeling, needs refreshing	\$ 12,390.00
3	Roller blinds, various classrooms	existing in disrepair, need replacing	\$ 7,500.00

Facility # 273Name: TTSC

Priority	Component Description	Component Deficiency	Estimate
1	Replace ceiling tiles Main Hall & Paint the ceiling areas	Tiles are old and stained	\$ 8,000.00

Facility # 509Name: VHSS

Priority	Component Description	Component Deficiency	Estimate
1	Pave driveway	existing is in poor condition, large pot holes	Capital
2	Privacy partitions	request from male students, want privacy	\$ 3,600.00
3	Roller blinds	existing in poor condition, not working	\$ 12,000.00
4	Flooring	various areas in bad shape	\$ 6,000.00
5	Painting, classrooms, ebase#129, 220, 228	flaking paint, requires patching	\$ 7,200.00

---

 PRIDE OF PLACE 2017
Facility # 507Name: WDHS

Priority	Component Description	Component Deficiency	Estimate
1	Cameras	update cameras on first and second floor	\$ 8,447.00
2	Roller blinds	none there	\$ 2,260.00
3	Painting, library	needs brightening up	\$ 2,875.00
5	Upgrades, small gym	where students work, doesn't look aesthetic	\$ 6,000.00
Total			\$650,000.00

